



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program May 25, 2006

Supervisor DRT

Mine Name: Lime Peak Quarries
Operator Name: Shaw Environmental, Inc.

Permit number: M/049 /047
Inspection Date, May 17, 2006
Time: 9:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Jeff Burningham
Mine Status: Active

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads,
8. Soils
9. Revegetation
10. Other

Weather: clear

Evaluated Comment Enforcement

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This inspection was done at the request of the operator.

Inspection Summary:

2. Access to the site is controlled by a gate (locked when not active) on the access road. Current highwall development has left benches with approximately 70-foot lift and 50-feet wide. A berm of material has been left on the south side of the last cut. This effectively screens (visual) much of the highwall from the south and east. Overall slope of the highwall is approximately 45 degrees. Back slope of the benches is currently about 70-75 degrees. Mr. Burningham indicated that sufficient material has now been removed from the pit to supply the needs for the next year or two. The last truck load of material was leaving the quarry when I arrived.
3. The overall grading of the pit (and highwalls) is in compliance and considered adequate for short-term inactivity. Final reclamation will require seeding of the benches and pit floor.

Conclusions and Recommendations:

2. Continue to monitor this site when in the area. Operator should notify Division prior to reactivation or final reclamation of the quarry area.

Photos were taken to document current conditions.

Inspector's Signature LK

LK:pb

cc: Tom Mathison, Operator

Date: May 25, 2006